

FIG.1

Sg = 0	0.01	0.05	0.10	0.15	0.20	0.25	0.30	0.35	0.40	0.45	0.50	0.55	SW
									.30				0.40
.0 Displ.1	.002	.014	.04	.08	.13	.20	.27	.36	.46	.57	.69	.83	0.44
		.0007	.02	.046	.081	.117	.205	.28	.39	.48	.57		0.50
		.0004	.011	.025	.042	.087	.14	.22	.30	.40			0.55
.0 Displ.3	.0002	.0017	.008	.0145	.032	.06	.105	.178	.25				0.60
		.00007	.00025	.0008	.019	.037	.070	.11					0.65
		.00003	.00012	.004	.01	.023	.045						0.70
		.0001	.0005			.0015							0.75
.0 Displ.2	.0												0.80





FIG.3



2/5

FIG.4





FIG.5



3/5




Fig.6A




Fig.6B




Fig.8

4/5

Fig.7





Fig.9

5/5




Fig.10